ID	Location	Floor	Room Elem	ent Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Approach and I	Entrance									
	Off-Street Parking Lot or Garage										
1	Police Station Entrance	Ext.	Off-St Parki or Ga	ng Lot		otal # of designated accessible parking spaces otal # of designated van accessible spaces Sign does not have the designation "Van Accessible" Sign bottom < 60" above finished grade	1 1 - 50"	Add the designation "Van Accessible" to the sign located at the van accessible space. Locate sign with the bottom of the sign 60" above the ground.	1	-	\$0
	Access to Good	ds and S	ervices								
	Means of Egr	ess									
2	Main Entrance/Exit	1	Mean: Egres			lluminated ISA symbol not provided (MAAB) actile exit sign not provided	- - -	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. Provide an illuminated sign with the International Symbol of Accessibility (ISA).	1	432	\$432
	Doors, Doorv	vays, & 0	Sates								
3	Public Interview Room	1	Doors Doon & Ga	vays,		//Aaneuvering clearance(s) not provided	-	Remove storage to maintain the required 18" min. clear floor space on the pull side of the door.	1	Labor	\$0
	Elevator										
4	Level E Elevator Entrance	1	Eleva	tor Interior	E	actile stars not provided at main entry level	-	Provide a tactile star on both sides of jambs at main floor. At other floors, provide appropriate number.	2	96	\$192

ID	Location	Floor	Room Elen	ent Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation	
	Signage											
5	Main Entrance	Ext.	Signa	ge Designation	AND	Raised characters not provided on sign Braille not provided on sign	-	Provide text with raised characters duplicated in braille on sign.	1	-	\$0	
	Assembly Are	ea		_								
6	Roll Call and Training Room	1	Assel Area	nbly N/A		Assistive listening devices not provided	-	If audible communication is integral to the use of the space, provide an assistive listening system.	1	1214	\$1214	
	Detention Fac	cilities										
7	By Entrance to Holding Cells	1	Deter Facili			. Clear floor space not provided at emergency shower	-	Relocate trash bins to ensure a 30" min. by 48" min. clear floor space is provided at the emergency shower.	1	Labor	\$0	
-	Γoilet & Bathin	g Rooms	;									
	Lavatory											
8	Men's and Women's Toilet Rooms Near Break Room	1	Lavat	ory N/A		Mirror above lavatory w/reflective surface > 40"	43"	Lower mirror so that the bottom surface is at 40" max. above the finished floor. Relocate paper towel dispenser so it is not mounted above the rear grab bar.	2	609	\$1218	

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
9	Single-User Toilet Room by the Lobby Area	1		Lavatory	461		Mirror above lavatory w/reflective surface > 40"	46"	Lower mirror so that the bottom surface is at 40" max. above the finished floor.	1	256	\$256
	Single-User T	oilet										
10	Women's Toilet Room Near Break Room	1		Single-User Toilet	N/A		Side or rear grab bar < 33" or > 36" high	31"	Mount side grab bars 33"- 36" above the finished floor. Relocate trash can to maintain the required 60" min. maneuvering clearance at the toilet.	1	396	\$396
11	Men's Toilet Room Near Break Room	1		Single-User Toilet	N/A		Side or rear grab bar < 33" or > 36" high	31"	Mount side grab bars 33"- 36" above the finished floor.	1	396	\$396
12	Single-User Toilet Room by the Lobby Area	1		Single-User Toilet	N/A		. Side or rear grab bar < 33" or > 36" high	30"	Mount grab bars 33"- 36" above the finished floor. Relocate trash can to maintain the required 60" min. maneuvering clearance at the toilet. Relocate paper towel dispenser so it is not mounted above the rear grab bar.	1	396	\$396
А	dditional Acce	ess										
	Drinking Fountains											
13	Near Roll Call	1		Drinking Fountains	Low		No drinking fountain provided for standing users	-	Provide an additional drinking fountain for standing users or install a Hi-Lo drinking fountain.	1	4028	\$4028

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
I	Best Practice										
	Bench										
14	Police Station Entrance	Ext.	Bench	N/A	IMPORTAL POLICE		res ind cai	ecommend providing a stable, firm and slip sistant surface adjacent to the bench so an dividual in a wheeled mobility or similar device in sit with his or her shoulders aligned with meone seated on the bench.	1	-	\$0
	Baby Changing Table										
15	Single-User Toilet Room by the Lobby Area	1	Baby Changing Table	N/A			the	nen renovation occurs, recommend locating e baby changing table 48" max. above the ished floor.	1	-	\$0
	Main Entrand	е									
16	Main Entrance	Ext.	Main Entrance	N/A	RANDOLPH POLICE		tea sui offi au ext	ecommend providing an automatic door. (IHCD am was told by the officers who took the rvey team through the building that both the icers and some visitors would like an tomatic door at the main entrance. While the terior door did not require excessive opening ace, some visitors have had difficulty with the or.)	1	-	\$0